

# NWFAA INDEX

## INDEX TO TECHNICAL MATTERS

“BEST PRACTICE”	-	Technical Bulletin # 14
“CURING” of COATING SYSTEMS	-	Technical Bulletin # 13
“DRUMMY” BLOCKS	-	Technical Bulletin # 14
“DRUMMY” FLOORS	-	Technical Bulletin # 14
“FULL CURING” of COATING SYSTEMS	-	Technical Bulletin # 7
“GOOD TRADE PRACTICE”	-	Technical Bulletin # 9
“HARDNESS” RATINGS	-	Technical Bulletin # 18
“JANKA” - HARDNESS RATINGS	-	Technical Bulletin # 18
“QUIET” FLOORS	-	Technical Bulletin # 14
“SET-DOWN” INFORMATION	-	Technical Bulletin # 14
“WARNING” - TO CONSUMERS & CONTRACTORS	-	Technical Bulletin # 14
“WARNING” - TO CONSUMERS	-	Technical Bulletin # 8
ACCLIMATISATION	-	Technical Bulletin # 14
ACCOUNTABILITY FOR WHOLE-OF-TRADE WORKS	-	Technical Bulletin # 5
ACOUSTICAL BLANKETS	-	Technical Bulletin # 17
ACOUSTICAL PLANK FLOORING	-	Technical Bulletin # 13
ACOUSTICAL RUBBER UNDERLAYS	-	Technical Bulletin # 16
ADHESIVE SYSTEMS	-	Technical Bulletin # 14
ADHESIVE USE	-	Technical Bulletin # 14
AIR CONDITIONING	-	Technical Bulletin # 14
ANCHORING (Fasteners & Recommended Method)	-	Technical Bulletin # 16
ANCHORING REQUIREMENTS - Structural Plywood Subfloors	-	Technical Bulletin # 16
ASSESSMENT OF SUB FLOOR SURFACE	-	Technical Bulletin # 14
ASSESSMENT OF THE SUB FLOOR	-	Technical Bulletin # 18
AUSTRALIAN STANDARDS	-	Technical Bulletin # 10
BAMBOO FLOORING	-	Technical Bulletin # 7
BEDDING-IN PROCESS	-	Technical Bulletin # 14
BELOW GRADE INSTALLATIONS	-	Technical Bulletin # 7
BREAK-POINTS	-	Technical Bulletin # 14
BUILDING CODE OF AUSTRALIA	-	Technical Bulletin # 7
CLIMATE ZONES	-	Technical Bulletin # 3
COATING SYSTEM WARNINGS	-	Technical Bulletin # 14
CONCRETE GRINDING & PREPARATION	-	Technical Bulletin # 16
CONCRETE MOISTURE METERS	-	Technical Bulletin # 18
CONTRACT ADVICE	-	Technical Bulletin # 13

CONTRACTORS	-	Technical Bulletin # 15
CORK EXPANSION JOINTS	-	Technical Bulletin # 14
CROSS-FLOW VENTILATION	-	Technical Bulletin # 3
DEFECTIVE SUB FLOORS	-	Technical Bulletin # 14
DIRECTION-of-LAY	-	Technical Bulletin # 14
DISPUTE RESOLUTION SERVICES	-	Technical Bulletin # 16
DRY GRINDING	-	Technical Bulletin # 18
EDGE BONDING	-	Technical Bulletin #5/7/14/16/18
ENVIRONMENTAL ASPECTS OF THE SITE	-	Technical Bulletin # 7
ENVIRONMENTAL CONSIDERATION	-	Technical Bulletin # 18
EXPANSION - Internal	-	Technical Bulletin # 14
EXPANSION - Perimeter	-	Technical Bulletin # 14
EXPANSION JOINTS – INTERMEDIATE	-	Technical Bulletin # 7
EXPANSION PROVISIONS	-	Technical Bulletin # 2
EXPOSED SLAB EDGES	-	Technical Bulletin # 7
FIT FOR PURPOSE	-	Technical Bulletin # 18
FLOATING FLOOR SYSTEMS	-	Technical Bulletin # 12
FLOOR COATING ADVICE	-	Technical Bulletin # 16
FLOOR COATING SYSTEMS - “Summer” Temperatures	-	Technical Bulletin # 6
FLOOR COATING SYSTEMS - “Winter Blues”	-	Technical Bulletin # 4
FLOOR COATINGS INFORMATION	-	Technical Bulletin # 18
FLOOR PROTECTORS	-	Technical Bulletin # 13
FRAUD	-	Technical Bulletin # 1
GEOGRAPHIC CONSIDERATIONS	-	Technical Bulletin # 2
GRINDING CONCRETE	-	Technical Bulletin # 16
HIGH HUMIDITY SITES	-	Technical Bulletin # 2/14
IDENTIFICATION OF TIMBER SPECIES	-	Technical Bulletin # 18
INSPECTION and REVIEW SERVICES	-	Technical Bulletin # 16
INSTALLATION METHODS	-	Technical Bulletin # 15
INSTALLATIONS	-	Technical Bulletin # 12
LAMINATE PLANK FLOORS	-	Technical Bulletin # 13
LEAKING SHOWERS	-	Technical Bulletin # 14
LETTING OF A CONTRACT	-	Technical Bulletin # 15
LIQUID VAPOUR PROOF MEMBRANES	-	Technical Bulletin # 12
MAGNESITE SUB FLOORS	-	Technical Bulletin # 14
MAINTENANCE	-	Technical Bulletin # 13
METHODS OF INSTALLATION	-	Technical Bulletin # 14
MOISTURE METERS	-	Technical Bulletin # 7
MOISTURE SEALS	-	Technical Bulletin # 18
MOISTURE TESTING - FLOORING SYSTEM	-	Technical Bulletin # 14
MOISTURE TESTING - SUB FLOORS	-	Technical Bulletin # 14
NON-APPROVED ACOUSTICAL MEMBRANES	-	Technical Bulletin # 15
PARQUET FLOORING - OVER CONCRETE	-	Technical Bulletin # 16
PARQUET FLOORS – OVER RUBBER UNDERLAYS	-	Technical Bulletin # 16
PLACEMENT OF FURNITURE	-	Technical Bulletin # 13

PLYWOOD SUB FLOORS	-	Technical Bulletin # 8/16
PREFINISHED ACOUSTICAL PLANK FLOORING	-	Technical Bulletin # 17
PROTECTION ADVICE	-	Technical Bulletin # 13
REPORTS & REPORT WRITING	-	Technical Bulletin # 9
REPORTS	-	Technical Bulletin # 16
RESPONSIBILITY OF A WOOD FLOOR CONTRACTOR-	-	Technical Bulletin # 18
RESPOSNSIBILITY FOR ASSESSING "SUITABILITY"	-	Technical Bulletin # 7
RUBBER UNDERLAYS	-	Technical Bulletin # 16
SECRET NAILING - SIZES	-	Technical Bulletin # 14
SILICON FILLED - EXPANSION VOIDS	-	Technical Bulletin # 7
SITE CONDITIONS	-	Technical Bulletin # 7
SITE DRAINAGE	-	Technical Bulletin #3/14
SPECIALIST WOOD FLOOR CONTRACTORS	-	Technical Bulletin # 5
SPECIES "CORRECTION" TABLES	-	Technical Bulletin # 18
STANDARDS AUSTRALIA	-	Technical Bulletin # 10
STRIP TIMBER FLOORS OVER CONCRETE	-	Technical Bulletin # 16
STRUCTURAL SHEET FLOORING "R" FLOOR	-	Technical Bulletin # 7
<b>SUB FLOOR LEVELS &amp; TOLERANCES</b>	-	Technical Bulletin #14/15/16/18
SUB FLOOR VENTILATION	-	Technical Bulletin #3/7
SUBSTITUTION OF TIMBER SPECIE	-	Technical Bulletin # 1
SUITABILITY OF SITE	-	Technical Bulletin # 18
TECHNICAL REPORTS	-	Technical Bulletin # 16
TENNANTED RESIDENCES	-	Technical Bulletin # 13
THERMAL ADVANTAGES OF WOOD	-	Technical Bulletin # 17
TIMBER GRADING	-	Technical Bulletin # 5
TIMBER MOISTURE METERS	-	Technical Bulletin # 18
TIMBER TRADER NEWS	-	Technical Bulletin # 11
TIPS AND TECHNICAL ADVICE	-	Technical Bulletin # 7
UNEVEN CONCRETE SUB FLOORS	-	Technical Bulletin # 15
UNSUITABLE SITES FOR WOOD FLOOR	-	Technical Bulletin # 12
VAPOUR PROOF MEMBRANES	-	Technical Bulletin # 12
WARRANTY ADVICE	-	Technical Bulletin #5/13
WATER BEAD TESTING	-	Technical Bulletin # 14
WATER DROP TESTING	-	Technical Bulletin # 18
WATER PROOFING	-	Technical Bulletin # 14
WOOD BLOCK PARQUET	-	Technical Bulletin # 14
WOOD FLOOR TRENDS IN AUSTRALIA	-	Technical Bulletin # 17